

January 5, 2010 11:35:46 AM

Item II	D:
Revisio	n I

DSI 9279-011

Accept



Setup Start



Stop

ID:

Item Name:

Strobe Power Supply Relocation

Start Date:

05/01/2010

Start Qty: 4.00 Req'd Qt: 4.00

Cust Item II:

Customer:

Reference:

Approvals:

Required Date: 18/01/2010

Date: 10-1-05 Tooling:

Date:

Run Start



SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours** Draw Number

Draw Rev.

Plan

Code

Accept Qty

Reject Reject Qty

Number Stamp

Draw Nbr

Revision Nbr

D3246

Rev A1

100

DOCUMENT CONTROL

Memo

0.00

0.00

Document Control

Photocopy bluefile and create labels as per PPP DSI 9279-011 CHG001

110

Pick Kit

0.00

Packaging Packaging

Memo

0.00

(c/4/27 (4)

120

QC4-100% Inspect kits for completeness

Quality Control

Memo

Dart Aeros	pace Ltd
------------	----------

W/O:	•		WO	RK ORDER CHANG	ES					<u> </u>
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
444							3 5			
Part No	:	PAR #:	Fault Categ	jory:	NCI	R: Yes	No DQ	\:	Date:	
		esolution:								
NCR:		1	WORK ORDE	R NON-CONFORMA	ANCE	(NCF	R)			
DATE	STEP	Description of NC		.,	ion B	<u>o</u> ;	Verific		Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		Sign 8 Date	Section	on C	Chief Eng	QC Inspector
	,			e e						
				The state of the s						

January 5, 2010 11:35:46 AM

Required Date: 18/01/2010

Item ID:

DSI 9279-011

Accept

Setup Start



Ston

Revision ID:

Item Name:

Strobe Power Supply Relocation

Start Date:

05/01/2010

Start Oty: 4.00

Reg' Oty: 4.00



Cust Item 12:

Customer

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Reses Start

Date:

SPC (Y/N):

Date:

Ston

Sequence ID/

Operation Work Center ID Description

Set Up/ Run Hours Draw Number Draw Rev.

Accept Qty Code

Plan

Reject Reject Oty

insp. Stamp Number

130

Packaging

Packaging

Packaging

0.00

0.00

Identify and pack for shipping as per PPP DSI 9279-011

140

QC.

Quality Control

OC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

10/04/28 XY-P/104-28

Dart Aerospace	Ltd
----------------	-----

	•									
W/O:			W	ORK ORDER CHANG	GES			··········	1,0	
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•		·								•
										ļ
- .							* *	!		
-,,					:					
Part No	:	PAR #:	Fault Cate	gory:	NCR	:Yes N	lo DQ	A:	_ Date: _	
	R	esolution:	Dispositio	n:	QA:	N/C Clo	sed:	·	Date:	
NCR:		-	WORK ORD	ER NON-CONFORM	IANCE	(NCR)				
DATE	STEP	Description of NC			ction B		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
								·····		
								-		
:										
I	1	ì	i i		1		1		I	I

Picklist Print Page 1 January 5, 2010 11:35:50 AM Work Order ID: 54985 Parent Item: DSI 9279-011 Required Date: 18/01/2010 Parent Item Name: Strobe Power Supply Relocation Start Date: 05/01/2010 Start Qty: 4.00 Required Qty: 4.00 Comments: Unit & Remaining Qty Date Replacement Mfg/ Bin Primary Last Route Qty on Component Item ID/ Status Qty To Pick Seq ID Measse Hand Issued Issued Item Location Location Item Name Item ID 🖲 Purch 1,128.000 16.0000 120 Each AN960JDIO No Purchased Washer Loc Qty Loc Code Warehouse NAO114900363J Location Main Warehouse ST 1128 38 105442 109059 2 109840 23 110139 2 110985 202 111279 5 111668 48 112314 78 112369 22 113149 738 0.0000 4.0000 120 Each Manufactured No MS27039-1-07 328.0000 16.0000 140 Each Purchased Screw Loc Qty Loc Code Warehouse Location Main Warehouse ST 328 18057 17 18106 311

Dart Aerospace Ltd


	•								~
W/O:			W	ORK ORDER CHANGE	S				جر, ,
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									i i
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	on:	QA: N/C CI	osed:		Date; _	
NCR:			WORK ORD	ER NON-CONFORMAI	NCE (NCR	()			
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
				x					
		·							
-	1						•		
								ļ	
1		•							







DES	ON DRAWN BY	DART AEROSPA	
CHE	KED APPROVED	DRAWING NO. D3246	REV. A SHEET 1 OF 1
DATE		TITLE	SCALE
04 A	04.21	MOUNTING BRACKET NEW ISSUE	1:4

CHANGE KIVET; ABOUD C'SINK



D3246-1 FLAT PATTERN





D3248-041_ASSEMBLY

RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

AN

WORK ORDER NO 54988

NOTES:

- MATERIAL: 2024-T3 (QQ-A-250/4) 0.050 THICK (REF. DART SPEC. M2024T3S.050)
 FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 ALL DIMENSIONS ARE IN INCHES
 BREAK ALL SHARP EDGES 0.005 TO 0.010

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dail Aciospace Lil	Dart	erospace Li	d
--------------------	------	-------------	---

W/O:			WC	RK ORDER CHANG	GES			· •	
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ļ.		
- Charleson		· :							
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	s No DC)A:	Date:	
	Re	esolution:	Disposition	n:	QA: N/C	Closed: _		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC		· · · · · · · · · · · · · · · · · · ·	ction B	Verif	ication	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		tion C	Chief Eng	-QC Inspector
					.				
									į.
							, · · ·		
s.									



[c	DESIGN	DRAWN BY	DART AEROSPACE LTD , HAWKESBURY, ONTARIO, CANADA
1	CHECKED.	APPROVED.	DRAWING NO. REV. A
	4	#	DSI 9279 SHEET 1 OF 2
10	DATE	.	TITLE SCALE
	04.04.22		STROBE POWER SUPPLY RELOCATION NTS
	Α	04.04.22	NEW ISSUE

REFERENCE ONLY

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION DRAWING D350-604 REV. B REF. CANADIAN STC: SH90-4 REF. FAA STC: SR00463NY

The purpose of this Service Instruction is to allow for relocation of power supply for the anticollision strobe light so that the D350-604-041 Rear Locker Extender can be properly installed in aircraft modified per SB 33.05.

Procedure:

- 1) Open luggage compartment and remove protective panels.
- 2) Position and transfer Ø0.129" (3.25mm) holes from D3246-041 Mounting Bracket to skin at (LH) side of the fuselage STA 195 as shown in the sketch. Install D3246-041 Mounting Bracket using (8) 21215 DC 24.07J/MS20470AD4 rivets
- 3) Disconnect tail boom electrical cables LX10E, LX11NE and LX12E from WHELEN A 490 ATS.DF Unit.
- 4) Remove WHELEN A 490 ATS.DF Unit from the original location at STA 203, by removing (4) 22272 BC 040.008L screws.
- 5) Install D350-604-041 Rear Locker Extender per Dart Installation Instruction D350-604.
- 6) Install WHELEN A 490 ATS.DF Unit to D3246-041 Mounting Bracket using (4) MS27039-1-07 Screws And (4) AN960JD10 Washers.
- 7) Re-route Cables LX10E, LX11NE and LX12E from the (RH) side to the (LH) side of the tail boom and re-connect to WHELEN A 490 ATS.DF Unit.
- 8) Re-connect Cables LX10E, LX11NE and LX12E
- 9) Check correct operation of anti-collision strobe light.
- 10) Touch up paint per the Aircraft Maintenance Manual to match original finish.
- 11) Refit luggage compartment inner protective panels.
- 12) Close luggage compartment door.

PARTS LIST

-011	Part Number	Description
Х	DSI 9279-011	STROBE POWER SUPPLY RELOCATION KIT
Fi	D3246-041 4 ^L	MOUNTING BRACKET
14	MS27039-1-07	SCREW
(4	AN960JD10 /	WASHER
,		

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE:
04.04.22
CERT. NO.:
SH90-4
ISSUE NO.: #3

Copyright © 2004 by DART AEROSPACE LTD

Dart Aerospace Li	td
--------------------------	----

W/O:	WORK ORDER CHANGES							•	,	
DATE	STEP	Approx						Approval Chief Eng /	Approval	
···	-					,		City	Prod Mgr	QC Inspector
										
Part No:		PAR #:	Fault Cate	dorv.	NCP: \	/os N	o DO	\	Deter	
Part No: PAR #:			Disposition: QA							
									Date:	
NCR:			WORK ORD	ER NON-CONFORM	IANCE (N	ICR)				
DATE	STEP	Description of NC	Corrective Action Section B				Verific	/erification	Approval	Approvai
	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Section C		Chief Eng	QC Inspector
										-
								·		